

Supplemental Type Certificate

Number ST01342WI-D

This certificate issued to:

Raytheon Aircraft Company
2400 Grundfest
Little Rock, AR 72206

certifies that the change in the type design for the following product with the limitations and conditions therefore as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation Regulations.

Original Product - Type Certificate Number : A3EU

Make : Raytheon Aircraft Company

Model : Hawker 800XP

Description of Type Design Change:

Installation of Collins Integrated Flight Information System (IFIS-5000) and Pro Line 21 Radios in accordance with (1) Collins Master Data List AAC-0404-001, Revision - , dated July 13, 2005; (2) Collins Airplane Flight Manual Supplement AAC-0406-001, Revision - , dated July 13, 2005; (3) Collins Maintenance Manual Supplement AAC-0407-001, Revision - , dated May 2, 2005; or later FAA approved revisions to (1), (2) or (3).

Limitations and Conditions:

(1) Prior installation and approval of Raytheon Aircraft Company Kit 149-3419-0001 is a prerequisite to this STC. (2) Prior installation and approval of Raytheon Aircraft Company Kit 149-3420-0001 is a prerequisite to this STC. (3) Compatibility of this design change with previously approved modifications must be determined by the installer. (4) If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : July 11, 2005

Date reissued : August 8, 2005

Date of issuance : July 13, 2005

Date amended :



By direction of the Administrator

Original signed by Harvey E. Nero

(Signature)

Harvey E. Nero

Program Manager

Wichita Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.